L Number	Hits	Search Text	DB	Time stamp
1	2	("6668615").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 17:39
2	15	("3408862" | "3667437" | "3946590" | "4254653" | "4359032" | "4437341" | "4903669" | "5143301" | "5241858" | "5535621" | "5634448" | "5641891" | "5806487" | "6260404" | "6359925").PN.	USPAT	2004/05/14 17:41
3	5650	(fuel adj inject$4) with (setting or calibrat$4 or adjust$4)	USPAT	2004/05/14 17:56
4	671	((fuel adj inject$4) with (setting or calibrat$4 or adjust$4)) and ((setting or calibrat$4 or adjust$4) with screw$4)	USPAT	2004/05/14 17:43
5	303	((fuel adj inject$4) with (setting or calibrat$4 or adjust$4)) and ((setting or calibrat$4 or adjust$4) with automat$4)	USPAT	2004/05/14 17:43
6	668	(fuel adj inject$4) and (automatic$4 near (setting or calibrat$4 or adjust$4))	USPAT	2004/05/14 17:57
7	6	((fuel adj inject$4) and (automatic$4 near (setting or calibrat$4 or adjust$4))) and (apparatus near calibrat$4)	USPAT	2004/05/14 17:57
8	25	(fuel adj inject$4) and (apparatus near calibrat$4)	USPAT	2004/05/14 17:57
9	3	4266426.URPN.	USPAT	2004/05/14 17:58
10	11599894	(73/1.71,1.36,119A).CCLS.c	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 18:00
11	990	(73/1.71,1.36,119A).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 18:12
13	65	(fuel with injector with calibrat$4).ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 18:59
14	1	"fuel injector" with (setting with station)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 19:00
15	1	"fuel injector" with (calibrat$4 with station)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 19:01
16	17	"fuel injector" with (calibrat$4 with apparatus)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 19:04
17	2	5226311.URPN.	USPAT	2004/05/14 19:02
18	13	("2756679" | "3267719" | "3404606" | "3407644" | "3487782" | "3495426" | "3597119" | "4041778" | "4214476" | "4286930" | "4362052" | "4625544" | "4864866").PN.	USPAT	2004/05/14 19:03
19	6	"fuel injector" with (calibrat$4 with machine)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 19:05
20	12	"fuel injector" with (calibrat$4 with device)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 19:05
-	66	73/1.71	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 10:49
-	47	(73/1.71).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:02

C:\APPS\EAST\Workspaces\10\10698548.wsp

-	30	(("3667437") or ("4254653") or ("5634448") or ("6260404") or ("5641891") or ("5143301") or ("3946590") or ("4359032") or ("5806487") or ("5535621") or ("4437341") or ("5241858") or ("3408862") or ("3946590") or ("4903669")).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 10:59
-	1	(("3667437") or ("4254653") or ("5634448") or ("6260404") or ("5641891") or ("5143301") or ("3946590") or ("4359032") or ("5806487") or ("5535621") or ("4437341") or ("5241858") or ("3408862") or ("3946590") or ("4903669")).PN.) and piezo$electric	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:04
-	943	(73/1.71,1.36,119A).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:03
-	268	((73/1.71,1.36,119A).CCLS.) and (calibrate or calibration or calibrating or setting)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:09
-	98	(((73/1.71,1.36,119A).CCLS.) and (calibrate or calibration or calibrating or setting)) and (fuel near injector$2)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:09
-	12	((((73/1.71,1.36,119A).CCLS.) and (calibrate or calibration or calibrating or setting)) and (fuel near injector$2)) and piezo$electric	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/05/14 17:59
-	4973	(fuel near injector$2) and (calibrate or calibration or calibrating or setting)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:09
-	848	((fuel near injector$2) and (calibrate or calibration or calibrating or setting)) and automatic	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 12:49
-	118	((fuel near injector$2) and (calibrate or calibration or calibrating or setting)) and (automatic with (calibrate or calibration or calibrating or setting))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 11:10
-	35	((fuel near injector$2) and (calibrate or calibration or calibrating or setting)) and (automatic and piezo$electric)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/08 12:50
-	232	((fuel near injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 10:58
-	531	((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:58
-	110	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and (measure or measuring) with (pressure)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:33
-	110	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((measure or measuring) with (pressure))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:36
-	0	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw with torque))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:37
-	17	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:56
-	8	("4529164" | "4584980" | "4725002" | "4907748" | "5092360" | "5779149" | "6085990" | "6148842").PN.	USPAT	2003/07/22 12:38

C:\APPS\EAST\Workspaces\10\10698548.wsp

-	0	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw with piezo$electric))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 13:23
-	0	(((injector$2) and (calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 12:58
-	19905	((calibrate or calibration or calibrating or setting)) and (piezo$electric)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 13:29
-	16	(((calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw with voltage))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 13:15
-	2	("3667437").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 13:15
-	33	(((calibrate or calibration or calibrating or setting)) and (piezo$electric)) and ((setting or adjustment or calibration) with (screw with piezo$electric))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 13:23
-	69	(((calibrate or calibration or calibrating or setting)) and (piezo$electric)) and (voltage with screw)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 14:24
-	11	(calibration near screw) with (torque)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/07/22 14:24